Approved F	or Release 2003/01/30 FCIA RDP81E00978	BR000600030184-5 Clops
2243Z 13 OCT 60 25X1A	SECRET	7 admin
DIRECTOR THE STREET ON THE STREET OF THE STREET ON THE STREET OF THE ST	4 AZEL 4	PRICEIV
RR 25X1A		IN 34406 25X1A
TOR: 2311Z 13 OCT 6	73195) 25X1A	0775
	ITEM 1 EXCEPT DATE ON 344 SHOU	ILD BE 8
NOV 1950.	OF UELD AT BURBANK HNTIL INS	TRUCTIONS

- 2. 343, 344 WILL BE HELD AT BURBANK UNTIL INSTRUCTIONS RECEIVED FROM HQs.
- 3. LAC OPINION RE 352 IS THAT AIRCRAFT NEED NOT BE ASSEMBLED AND FLOWN PRIOR TO DELIVERY TO ITS DESTINATION. WE FEEL REGULAR EXPERIENCED U2 MECHANICS CAN HAVE ARTICLE IN AIR IN MINIMUM TIME AFTER ARRIVAL AT DESTINATION. HYD PLUMBING AND FUEL TANK LEAKS HAVE NOT BEEN A PROBLEM IN THE PAST DUE TO FAIRLY LONG STORAGE TIME ON ARTICLES.

END OF MESSAGE

DOCUMENT NO. NO CHANCE IN CLASS. []
EL BUCLACSIFIED CLASS CHANGED TO: TS SCO
IDEXT REVIEW DATE: AUTH: HB 70-2
DATE: 2/12/41 REVIEWER:

25X1A